



# Motor Vehicle Safety Recalls Database

- [New Search](#)
- [Advanced Search](#)
- [Modify Search](#)
- [Main Menu](#) ▼

[Motor Vehicle Safety](#) > [Vehicle Recalls and Defects](#) > [Motor Vehicle Safety Recalls Database](#)

## Recall Details

### Transport Canada Recall # 2024-068

<b>Recall Date</b>	2024-02-05
<b>Last Updated</b>	2024-02-07
<b>Notification Type</b>	Compliance Mfr
<b>System</b>	Visual System
<b>Issued by</b>	NISSAN
<b>Manufacturer Recall Number</b>	
<b>Units Affected</b> <small> ⓘ</small>	11,985
<b>Category</b>	Car

#### Recall Details

**Issue:**

On certain vehicles, the rearview camera wiring harness could be damaged by movement and vibrations. If this happens, the rearview camera image may not display correctly or may not display at all. Canadian regulations require the rearview image to display when reversing.

**Safety Risk:**

A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash.

**Corrective Actions:**

Nissan will notify owners by mail. The corrective actions for this recall are under development.

Make	Model	Model Year(s) Affected
NISSAN	LEAF	2018 2019 2020 2021 2022

Make	Contact Number	Web Site
NISSAN	1-	<a href="http://service.nissan.ca/en/vin-recall">service.nissan.ca/en/vin-recall</a>

#### Canadian Motor Vehicle Safety Standards (CMVSS)

Number	Description
111	Mirrors and Rear Visibility Systems

[Report a problem on this page](#)

[Share this page](#)

[Terms and conditions](#) • [Privacy](#)

Canada 